Measure clear glass width and drop • min. width: 325mm · max. width: 1400mm

• max. drop: 2000mm Type 1 Fabrics 1700mm Type 2 Fabrics

1200mm Type 3 Fabrics

• max. area: 2m²



N.B. Please ensure windows have suitable rubber bead that accepts fitting of bracket





Depth Gauge (TP487)



Max. Bead Depth 27mm Min. Bead Depth 11mm

Proud Rubber Bead


Ensure windows have suitable rubber bead that accepts fitting of bracket


B

bead depth


side profile







Side Extrusion: Large



Less than 1mm


Select side extrusion that gives smallest gap between extrusion and window bead (x)

Where the gap is greater

size (both sides).

than 1mm. The size MUST BE

deducted from the clear glass



Greater than 1mm

best fit profile

best fit

E




special headrail



70mm std. 50mm mod.

Reduced Headrail

- insufficient clearance on window frame or glazing bar will require modified headrails
- reduction will be 10mm per side
- note requirements on order form 'Special Instructions' box





vent

measure


here (y)

Air Vents

When headrail may foul air vent or other obstruction, a deduction of up to 10mm can be made from the clear glass size (drop).

This can be measured by using a small section of headrail fascia fitted with a fixing bracket.

Enter drop (a) on order form (x-y+a)



Bottom bar




Bottom Bar

When installation is complete, clearance between bottom bar endcap and side extrusion should be checked. This should be parallel along entire length of side extrusion. This can be checked by holding bottom bar tight against one side and measuring the clearance on the opposite side.

Max. clearance: 3mm



When window is slightly out of square, spacer pads should be used to ensure side extrusions run parallel.



Fabric Alignment

Blind should be checked when installation is complete to ensure that fabric is rolling up parallel. Where this is not the case the blind can be adjusted by moving one side extrusion up or down within the ratchet lock area. This will in turn induce the fabric to roll to one side as required.

eg. If fabric is rolling off to left hand side, lower right hand corner bracket. This can be done by releasing the side extrusion locking bracket from the ratchet lock, slide corner bracket down, lock side extrusion back in to ratchet lock.



Blind unocked

Headrail Lock

After installation ensure that headrail locking arm is fully engaged. This can be checked by looking from below to ensure locking arm is sitting parallel with mating bracket.

It is important to ensure that blind is always left in the locked position.



Blind locked